

**RAILROAD COMMISSION OF TEXAS  
HEARINGS DIVISION**

**OIL & GAS DOCKET NO. 20-0284224**

---

**IN RE: P-5 ORGANIZATION REPORT OF SUNDANCE CONSULTING CORP.**

---

**FINAL ORDER**

The Commission finds that after notice and an opportunity for hearing regarding the captioned matter, the Operator failed to request a hearing and pay the hearing fee as required by 16 TEX. ADMIN. CODE §3.15(g)(4) and TEX. NAT. RES. CODE §89.022(f). This matter having been duly submitted to the Railroad Commission of Texas at conference held in its offices in Austin, Texas, the Commission makes the following findings of fact and conclusions of law.

**FINDINGS OF FACT**

1. Sundance Consulting Corp. [Operator #829459] (the "Operator"), is the record operator or one or more inactive wells in the State of Texas and is required to file Organization Report (Form P-5) with the Commission. Operator's most recent P-5 was due on or before April 1, 2013.
2. After filing its most recent Organization Report (Form P-5) with the Commission, the Operator was notified they were deficient and had failed to comply with the requirements of 16 TEX. ADMIN. CODE § 3.15 (Surface Equipment Removal Requirements and Inactive Wells) and provided with a written statement of the reasons for the determination and allowed ninety (90) days from the date its P-5 was due to comply with the requirements of 16 TEX. ADMIN. CODE § 3.15 and TEX. NAT. RES. CODE §§89.021 - 89.030.
3. After the expiration of ninety (90) days and pursuant to 16 TEX. ADMIN CODE §3.15(g)(4), an authorized Commission employee determined that the Operator's Organization Report still could not be renewed because the Operator continued to fail to comply with the requirements of 16 TEX. ADMIN. CODE §3.15 (Surface Equipment Removal Requirements and Inactive Wells).
4. The Commission sent the Operator a letter by certified mail giving notice to the Operator of the determination of continued non-compliance regarding specified inactive wells, attached as Exhibit A to this order, and advising the Operator of the right to request a hearing to show compliance. The letter notified the Operator that the hearing request must be received in docket services no later than 30 days after the date of the letter. The letter also notified the Operator that a final order denying renewal of the Operator's Organization Report (Form P-5) would result in the cancellation of all P-4 Certificates of Compliance and the severance of all pipeline or other carrier connections.

5. All notices and letters from the Commission to the Operator on this matter were addressed and mailed to the Operator's most recently reported address on the Form P-5 Organization Report.
6. The Operator did not timely request a hearing and pay the hearing fee on these issues as required under 16 TEX. ADMIN. CODE §3.15(g)(4) (Surface Equipment Removal Requirements and Inactive Wells).
7. Statewide Rule 15 (16 TEX. ADMIN. CODE §3.15) is a Commission rule that relates to safety or the prevention or control of pollution.

**CONCLUSIONS OF LAW**

1. The Operator received proper notice and an opportunity for hearing regarding compliance with 16 Tex. Admin. Code §3.15 and Tex. Nat. Res. Code §§89.021 - 89.030.
2. All things necessary to the Commission attaining jurisdiction over the subject matter and the parties in this matter have been performed or have occurred.
3. The Operator is in violation of Commission Statewide Rule 15 and did not timely request a hearing to contest the determination that it was in violation.
4. The Operator's P-5 Organization Report should not be renewed and all of the Operator's P-4 Certificates of Compliance should be cancelled, with all related pipeline or other carrier connections severed. 16 Tex. Admin. Code §3.15 (g)(4) and Tex. Nat. Res. Code §§89.022(f), 91.704 - 91.706.
5. The Operator's P-5 Organization Report cannot be renewed until the operator brings the inactive wells shown on the attached Exhibit A into compliance with the requirements of 16 Tex. Admin. Code §3.15 and Tex. Nat. Res. Code §§89.021 - 89.030.

**IT IS ORDERED** that renewal of Sundance Consulting Corp.'s P-5 Organization Report is hereby **DENIED**.

**It is further ORDERED** that all P-4 Certificates of Compliance issued to Sundance Consulting Corp. as operator of record are hereby **CANCELLED** and all related pipeline or other carrier connections are hereby **SEVERED**.

**It is further ORDERED** that Sundance Consulting Corp. shall bring the wells on Exhibit A into compliance with Statewide Rule 15 (16 TEX. ADMIN. CODE §3.15) and that the Operator's P-5 Organization Report shall not be renewed until the wells on Exhibit A have been brought into compliance as required by this order.

**It is further ORDERED** that Sundance Consulting Corp. and each person who held a position of ownership or control in the Operator at the time the Operator's most-recent P-5 Organization Report was filed shall be subject to the terms of TEX. NAT. RES. CODE §91.114.

**It is further ORDERED** by the Commission that this order shall not be final and effective until 20 days after a party is notified of the Commission's order. A party is presumed to have been notified of the Commission's order three days after the date on which the notice is actually mailed. If a timely motion for rehearing is filed by any party at interest, this order shall not become final and effective until such motion is overruled, or if such motion is granted, this order shall be subject to further action by the Commission. Pursuant to TEX. GOV'T. CODE §2001.146(e), the time allotted for Commission action on a motion for rehearing in this case prior to its being overruled by operation of law, is hereby extended until 90 days from the date the parties are notified of the order.

All requested Findings of Fact and Conclusions of Law which are not expressly adopted herein are **DENIED**. All pending motions and request for relief not previously granted or granted herein are **DENIED**.

**RAILROAD COMMISSION OF TEXAS**

(Signatures affixed by Rule 15 Inactive Well  
Master Order dated September 10, 2013.)

API Number	District	ID Number	Lease Name	Well Number
253 34880	7B	07108	CITY OF ABILENE	3
Electricity must be disconnected (certify on Form W-3C)				
No approved W-3X on file				
253 80688	7B	07108	CITY OF ABILENE	1
Electricity must be disconnected (certify on Form W-3C)				
Production fluids must be purged (certify on Form W-3C)				
No approved W-3X on file				
Must resolve Field Operations H-15 delinquency preventing 14B2 approval				
253 80689	7B	07108	CITY OF ABILENE	2
Electricity must be disconnected (certify on Form W-3C)				
Surface equipment must be removed (certify on Form W-3C)				
No approved W-3X on file				
Must resolve Field Operations H-15 delinquency preventing 14B2 approval				
417 33099	7B	15659	ANDREWS, FRANK	1
Electricity must be disconnected (certify on Form W-3C)				
No approved W-3X on file				
417 33591	7B	15659	ANDREWS, FRANK	3
Electricity must be disconnected (certify on Form W-3C)				
Surface equipment must be removed (certify on Form W-3C)				
No approved W-3X on file				
417 34013	7B	15659	ANDREWS, FRANK	4
Electricity must be disconnected (certify on Form W-3C)				
Surface equipment must be removed (certify on Form W-3C)				
No approved W-3X on file				
417 34647	7B	15659	ANDREWS, FRANK	5
Electricity must be disconnected (certify on Form W-3C)				
Surface equipment must be removed (certify on Form W-3C)				
No approved W-3X on file				
417 34714	7B	15659	ANDREWS, FRANK	6
Electricity must be disconnected (certify on Form W-3C)				
No approved W-3X on file				
417 34778	7B	15659	ANDREWS, FRANK	7
Electricity must be disconnected (certify on Form W-3C)				
Surface equipment must be removed (certify on Form W-3C)				
No approved W-3X on file				
417 34779	7B	15659	ANDREWS, FRANK	8
Electricity must be disconnected (certify on Form W-3C)				
No approved W-3X on file				
417 34981	7B	15659	ANDREWS, FRANK	9
Electricity must be disconnected (certify on Form W-3C)				
Surface equipment must be removed (certify on Form W-3C)				
No approved W-3X on file				
Must resolve UIC H-5 Test issue preventing 14(B)(2) approval				
417 35002	7B	15659	ANDREWS, FRANK	10
Electricity must be disconnected (certify on Form W-3C)				
No approved W-3X on file				

Docket No. 20-0284224

Exhibit A

API Number	District	ID Number	Lease Name	Well Number
417 35040	7B	15659	ANDREWS, FRANK	12
Electricity must be disconnected (certify on Form W-3C)				
No approved W-3X on file				
Must resolve UIC H-5 Test issue preventing 14(B)(2) approval				
417 35085	7B	15659	ANDREWS, FRANK	13
Electricity must be disconnected (certify on Form W-3C)				
Surface equipment must be removed (certify on Form W-3C)				
No approved W-3X on file				
417 35189	7B	15659	ANDREWS, FRANK	15
Electricity must be disconnected (certify on Form W-3C)				
Surface equipment must be removed (certify on Form W-3C)				
No approved W-3X on file				
417 35190	7B	20068	ANDREWS, FRANK "A"	1
Electricity must be disconnected (certify on Form W-3C)				
Surface equipment must be removed (certify on Form W-3C)				
No approved W-3X on file				
Must resolve Field Operations H-15 delinquency preventing 14B2 approval				
417 35270	7B	15659	ANDREWS, FRANK	16
Electricity must be disconnected (certify on Form W-3C)				
Surface equipment must be removed (certify on Form W-3C)				
No approved W-3X on file				
417 35271	7B	15659	ANDREWS, FRANK	17
Electricity must be disconnected (certify on Form W-3C)				
Surface equipment must be removed (certify on Form W-3C)				
No approved W-3X on file				
417 35331	7B	15659	ANDREWS, FRANK	21
Electricity must be disconnected (certify on Form W-3C)				
No approved W-3X on file				
417 35332	7B	15659	ANDREWS, FRANK	20
Electricity must be disconnected (certify on Form W-3C)				
Surface equipment must be removed (certify on Form W-3C)				
No approved W-3X on file				
417 35334	7B	15659	ANDREWS, FRANK	19
Electricity must be disconnected (certify on Form W-3C)				
Surface equipment must be removed (certify on Form W-3C)				
No approved W-3X on file				
417 35552	7B	15659	ANDREWS, FRANK	23
Electricity must be disconnected (certify on Form W-3C)				
No approved W-3X on file				
417 35553	7B	15659	ANDREWS, FRANK	24
Electricity must be disconnected (certify on Form W-3C)				
Surface equipment must be removed (certify on Form W-3C)				
No approved W-3X on file				
417 35590	7B	15659	ANDREWS, FRANK	25
Electricity must be disconnected (certify on Form W-3C)				
Surface equipment must be removed (certify on Form W-3C)				
No approved W-3X on file				

Docket No. 20-0284224

Exhibit A

API Number	District	ID Number	Lease Name	Well Number
417 35591	7B	15659	ANDREWS, FRANK	26
Electricity must be disconnected (certify on Form W-3C)				
Surface equipment must be removed (certify on Form W-3C)				
No approved W-3X on file				
417 35592	7B	15659	ANDREWS, FRANK	27
Electricity must be disconnected (certify on Form W-3C)				
Surface equipment must be removed (certify on Form W-3C)				
No approved W-3X on file				
417 35618	7B	15659	ANDREWS, FRANK	28
Electricity must be disconnected (certify on Form W-3C)				
Surface equipment must be removed (certify on Form W-3C)				
No approved W-3X on file				
417 35631	7B	15659	ANDREWS, FRANK	29
Electricity must be disconnected (certify on Form W-3C)				
Surface equipment must be removed (certify on Form W-3C)				
No approved W-3X on file				
417 35632	7B	15659	ANDREWS, FRANK	30
Electricity must be disconnected (certify on Form W-3C)				
Surface equipment must be removed (certify on Form W-3C)				
No approved W-3X on file				
417 35658	7B	15659	ANDREWS, FRANK	34
Electricity must be disconnected (certify on Form W-3C)				
Surface equipment must be removed (certify on Form W-3C)				
No approved W-3X on file				
417 35661	7B	15659	ANDREWS, FRANK	33
Electricity must be disconnected (certify on Form W-3C)				
No approved W-3X on file				
417 35662	7B	15659	ANDREWS, FRANK	31
Electricity must be disconnected (certify on Form W-3C)				
No approved W-3X on file				
417 35663	7B	15659	ANDREWS, FRANK	32
Electricity must be disconnected (certify on Form W-3C)				
Surface equipment must be removed (certify on Form W-3C)				
No approved W-3X on file				
417 35682	7B	15659	ANDREWS, FRANK	36
Electricity must be disconnected (certify on Form W-3C)				
No approved W-3X on file				
417 35683	7B	15659	ANDREWS, FRANK	38
Electricity must be disconnected (certify on Form W-3C)				
Surface equipment must be removed (certify on Form W-3C)				
No approved W-3X on file				
417 35684	7B	15659	ANDREWS, FRANK	37
Electricity must be disconnected (certify on Form W-3C)				
Surface equipment must be removed (certify on Form W-3C)				
No approved W-3X on file				

Docket No. 20-0284224

Exhibit A

API Number	District	ID Number	Lease Name	Well Number
417 35686	7B	15659	ANDREWS, FRANK	35
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
417 35732	7B	15659	ANDREWS, FRANK	44
Electricity must be disconnected (certify on Form W-3C) Surface equipment must be removed (certify on Form W-3C) No approved W-3X on file				
417 35733	7B	15659	ANDREWS, FRANK	43
Electricity must be disconnected (certify on Form W-3C) Surface equipment must be removed (certify on Form W-3C) No approved W-3X on file				
417 35734	7B	15659	ANDREWS, FRANK	42
Electricity must be disconnected (certify on Form W-3C) Surface equipment must be removed (certify on Form W-3C) No approved W-3X on file				
417 35735	7B	15659	ANDREWS, FRANK	41
Electricity must be disconnected (certify on Form W-3C) Surface equipment must be removed (certify on Form W-3C) No approved W-3X on file				
417 35736	7B	15659	ANDREWS, FRANK	40
Electricity must be disconnected (certify on Form W-3C) Surface equipment must be removed (certify on Form W-3C) No approved W-3X on file				
417 35777	7B	15659	ANDREWS, FRANK	49
Electricity must be disconnected (certify on Form W-3C) Surface equipment must be removed (certify on Form W-3C) No approved W-3X on file				
417 35779	7B	15659	ANDREWS, FRANK	47
Electricity must be disconnected (certify on Form W-3C) Surface equipment must be removed (certify on Form W-3C) No approved W-3X on file				
417 35780	7B	15659	ANDREWS, FRANK	46
Electricity must be disconnected (certify on Form W-3C) Surface equipment must be removed (certify on Form W-3C) No approved W-3X on file				
417 35781	7B	15659	ANDREWS, FRANK	45
Electricity must be disconnected (certify on Form W-3C) Surface equipment must be removed (certify on Form W-3C) No approved W-3X on file				
417 35923	7B	15659	ANDREWS, FRANK	11
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
417 35956	7B	21608	ANDREWS, FRANK "B"	1
Electricity must be disconnected (certify on Form W-3C) Surface equipment must be removed (certify on Form W-3C) No approved W-3X on file				

Docket No. 20-0284224

Exhibit A

API Number	District	ID Number	Lease Name	Well Number
417 35957	7B	21608	ANDREWS, FRANK "B" Electricity must be disconnected (certify on Form W-3C) Surface equipment must be removed (certify on Form W-3C) No approved W-3X on file	2B
417 35991	7B	21608	ANDREWS, FRANK "B" Electricity must be disconnected (certify on Form W-3C) Surface equipment must be removed (certify on Form W-3C) No approved W-3X on file	5B
417 35992	7B	21608	ANDREWS, FRANK "B" Electricity must be disconnected (certify on Form W-3C) Surface equipment must be removed (certify on Form W-3C) No approved W-3X on file	3
417 36108	7B	21608	ANDREWS, FRANK "B" Electricity must be disconnected (certify on Form W-3C) Surface equipment must be removed (certify on Form W-3C) No approved W-3X on file	6B

INSUFFICIENT PROGRESS ON 10-YEAR INACTIVE WELLS: For wells shut-in at least 10 years as of September 1, 2010, operators were given five years to address the surface equipment removal requirements. For your Organization Report renewal on APRIL 1, 2013, Rule 15(i) requires that you be at least 40% complete with this process. Current W-3C records indicate that you have not met this requirement (0% of your phase-in wells show that you have completed the surface cleanup). Your Organization Report renewal cannot be approved until you have met this requirement and have filed the appropriate Commission forms to update our records.

Docket No. 20-0284224

Exhibit A