

**RAILROAD COMMISSION OF TEXAS
HEARINGS DIVISION**

OIL & GAS DOCKET NO. 20-0294666

IN RE: P-5 ORGANIZATION REPORT OF MIDWESTERN ENERGY

FINAL ORDER

The Commission finds that after notice and an opportunity for hearing regarding the captioned matter, the Operator failed to request a hearing and pay the hearing fee as required by 16 TEX. ADMIN. CODE §3.15(g)(4) and TEX. NAT. RES. CODE §89.022(f). This matter having been duly submitted to the Railroad Commission of Texas at conference held in its offices in Austin, Texas, the Commission makes the following findings of fact and conclusions of law.

FINDINGS OF FACT

1. Midwestern Energy [Operator #566592] (the "Operator"), is the record operator or one or more inactive wells in the State of Texas and is required to file Organization Report (Form P-5) with the Commission. Operator's most recent P-5 was due on or before August 1, 2014.
2. After filing its most recent Organization Report (Form P-5) with the Commission, the Operator was notified they were deficient and had failed to comply with the requirements of 16 TEX. ADMIN. CODE § 3.15 (Surface Equipment Removal Requirements and Inactive Wells) and provided with a written statement of the reasons for the determination and allowed ninety (90) days from the date its P-5 was due to comply with the requirements of 16 TEX. ADMIN. CODE § 3.15 and TEX. NAT. RES. CODE §§89.021 - 89.030.
3. After the expiration of ninety (90) days and pursuant to 16 TEX. ADMIN CODE §3.15(g)(4), an authorized Commission employee determined that the Operator's Organization Report still could not be renewed because the Operator continued to fail to comply with the requirements of 16 TEX. ADMIN. CODE §3.15 (Surface Equipment Removal Requirements and Inactive Wells).
4. The Commission sent the Operator a letter by certified mail giving notice to the Operator of the determination of continued non-compliance regarding specified inactive wells, attached as Exhibit A to this order, and advising the Operator of the right to request a hearing to show compliance. The letter notified the Operator that the hearing request must be received in docket services no later than 30 days after the date of the letter. The letter also notified the Operator that a final order denying renewal of the Operator's Organization Report (Form P-5) would result in the cancellation of all P-4 Certificates of Compliance and the severance of all pipeline or other carrier connections.

5. All notices and letters from the Commission to the Operator on this matter were addressed and mailed to the Operator's most recently reported address on the Form P-5 Organization Report.
6. The Operator did not timely request a hearing and pay the hearing fee on these issues as required under 16 TEX. ADMIN. CODE §3.15(g)(4) (Surface Equipment Removal Requirements and Inactive Wells).
7. Statewide Rule 15 (16 TEX. ADMIN. CODE §3.15) is a Commission rule that relates to safety or the prevention or control of pollution.

CONCLUSIONS OF LAW

1. The Operator received proper notice and an opportunity for hearing regarding compliance with 16 Tex. Admin. Code §3.15 and Tex. Nat. Res. Code §§89.021 - 89.030.
2. All things necessary to the Commission attaining jurisdiction over the subject matter and the parties in this matter have been performed or have occurred.
3. The Operator is in violation of Commission Statewide Rule 15 and did not timely request a hearing to contest the determination that it was in violation.
4. The Operator's P-5 Organization Report should not be renewed and all of the Operator's P-4 Certificates of Compliance should be cancelled, with all related pipeline or other carrier connections severed. 16 Tex. Admin. Code §3.15 (g)(4) and Tex. Nat. Res. Code §§89.022(f), 91.704 - 91.706.
5. The Operator's P-5 Organization Report cannot be renewed until the operator brings the inactive wells shown on the attached Exhibit A into compliance with the requirements of 16 Tex. Admin. Code §3.15 and Tex. Nat. Res. Code §§89.021 - 89.030.

IT IS ORDERED that renewal of Midwestern Energy's P-5 Organization Report is hereby **DENIED**.

It is further ORDERED that all P-4 Certificates of Compliance issued to Midwestern Energy as operator of record are hereby **CANCELLED** and all related pipeline or other carrier connections are hereby **SEVERED**.

It is further ORDERED that Midwestern Energy shall bring the wells on Exhibit A into compliance with Statewide Rule 15 (16 TEX. ADMIN. CODE §3.15) and that the Operator's P-5 Organization Report shall not be renewed until the wells on Exhibit A have been brought into compliance as required by this order.

It is further ORDERED that Midwestern Energy and each person who held a position of ownership or control in the Operator at the time the Operator's most-recent P-5 Organization Report was filed shall be subject to the terms of TEX. NAT. RES. CODE §91.114.

It is further ORDERED by the Commission that this order shall not be final and effective until 20 days after a party is notified of the Commission's order. A party is presumed to have been notified of the Commission's order three days after the date on which the notice is actually mailed. If a timely motion for rehearing is filed by any party at interest, this order shall not become final and effective until such motion is overruled, or if such motion is granted, this order shall be subject to further action by the Commission. Pursuant to TEX. GOV'T. CODE §2001.146(e), the time allotted for Commission action on a motion for rehearing in this case prior to its being overruled by operation of law, is hereby extended until 90 days from the date the parties are notified of the order.

All requested Findings of Fact and Conclusions of Law which are not expressly adopted herein are **DENIED**. All pending motions and request for relief not previously granted or granted herein are **DENIED**.

RAILROAD COMMISSION OF TEXAS

(Signatures affixed by Rule 15 Inactive Well
Master Order dated January 27, 2015.)

API Number	District	ID Number	Lease Name	Well Number
009 33701 No approved W-3X on file	09	19452	AMINEX -A-	A 1
009 33906 No approved W-3X on file	09	19452	AMINEX -A-	A 2
009 33907 No approved W-3X on file	09	19452	AMINEX -A-	A 3
009 34109 No approved W-3X on file	09	19452	AMINEX -A-	1D
009 34435 No approved W-3X on file	09	19452	AMINEX -A-	8A
009 34971 No approved W-3X on file	09	19452	AMINEX -A-	4
009 35275 No approved W-3X on file	09	19452	AMINEX -A-	9
009 35959 No approved W-3X on file	09	19452	AMINEX -A-	10
009 36659 No approved W-3X on file	09	19452	AMINEX -A-	11
023 31140 No approved W-3X on file	09	25053	KOLACEK	1
275 00871 No approved W-3X on file	09	08400	HUNT, E. W.	1
275 30628 Surface equipment must be removed (certify on Form W-3C) No approved W-3X on file Must resolve UIC H-5 Test issue preventing 14(B)(2) approval	09	09979	ZEISSEL	6
275 30875 No approved W-3X on file	09	08400	HUNT, E. W.	9
275 80030 No approved W-3X on file	09	08400	HUNT, E. W.	6
275 80083 No approved W-3X on file	09	08400	HUNT, E. W.	C 1
275 80312 No approved W-3X on file	09	09979	ZEISSEL	2
353 00534 No approved W-3X on file Must resolve UIC H-5 Test issue preventing 14(B)(2) approval	7B	25971	GROUP 4000 UNIT "A"	14
353 32150 No approved W-3X on file	7B	25971	GROUP 4000 UNIT "A"	23A

Docket No. 20-0294666

Exhibit A

API Number	District	ID Number	Lease Name	Well Number
353 32157 No approved W-3X on file	7B	25971	GROUP 4000 UNIT "A"	16 A
353 32170 No approved W-3X on file	7B	25971	GROUP 4000 UNIT "A"	9A
353 32231 No approved W-3X on file	7B	25971	GROUP 4000 UNIT "A"	15 A
353 80624 No approved W-3X on file	7B	10432	GROUP 4000 UNIT	39
485 86755 No approved W-3X on file	09	06069	STATE LEASE NO. 42585	G 1
485 87151 No approved W-3X on file	09	06310	STATE LEASE NO. 42585	2

Docket No. 20-0294666

Exhibit A