

**RAILROAD COMMISSION OF TEXAS
HEARINGS DIVISION**

OIL & GAS DOCKET NO. 20-0305041

IN RE: P-5 ORGANIZATION REPORT OF RENEAU OIL CO.

FINAL ORDER

The Commission finds that after notice and an opportunity for hearing regarding the captioned matter, the Operator failed to request a hearing and pay the hearing fee as required by 16 TEX. ADMIN. CODE §3.15(g)(4) and TEX. NAT. RES. CODE §89.022(f). This matter having been duly submitted to the Railroad Commission of Texas at conference held in its offices in Austin, Texas, the Commission makes the following findings of fact and conclusions of law.

FINDINGS OF FACT

1. Reneau Oil Co. [Operator #701746] (the “Operator”), is the record operator or one or more inactive wells in the State of Texas and is required to file Organization Report (Form P-5) with the Commission. Operator’s most recent P-5 was due on or before January 1, 2016.
2. After filing its most recent Organization Report (Form P-5) with the Commission, the Operator was notified they were deficient and had failed to comply with the requirements of 16 TEX. ADMIN. CODE § 3.15 (Surface Equipment Removal Requirements and Inactive Wells) and provided with a written statement of the reasons for the determination and allowed ninety (90) days from the date its P-5 was due to comply with the requirements of 16 TEX. ADMIN. CODE § 3.15 and TEX. NAT. RES. CODE §§89.021 - 89.030.
3. After the expiration of ninety (90) days and pursuant to 16 TEX. ADMIN CODE §3.15(g)(4), an authorized Commission employee determined that the Operator’s Organization Report still could not be renewed because the Operator continued to fail to comply with the requirements of 16 TEX. ADMIN. CODE §3.15 (Surface Equipment Removal Requirements and Inactive Wells).
4. The Commission sent the Operator a letter by certified mail giving notice to the Operator of the determination of continued non-compliance regarding specified inactive wells, attached as Exhibit A to this order, and advising the Operator of the right to request a hearing to show compliance. The letter notified the Operator that the hearing request must be received in docket services no later than 30 days after the date of the letter. The letter also notified the Operator that a final order denying renewal of the Operator’s Organization Report (Form P-5) would result in the cancellation of all P-4 Certificates of Compliance and the severance of all pipeline or other carrier connections.

5. All notices and letters from the Commission to the Operator on this matter were addressed and mailed to the Operator's most recently reported address on the Form P-5 Organization Report.
6. The Operator did not timely request a hearing and pay the hearing fee on these issues as required under 16 TEX. ADMIN. CODE §3.15(g)(4) (Surface Equipment Removal Requirements and Inactive Wells).
7. Statewide Rule 15 (16 TEX. ADMIN. CODE §3.15) is a Commission rule that relates to safety or the prevention or control of pollution.

CONCLUSIONS OF LAW

1. The Operator received proper notice and an opportunity for hearing regarding compliance with 16 Tex. Admin. Code §3.15 and Tex. Nat. Res. Code §§89.021 - 89.030.
2. All things necessary to the Commission attaining jurisdiction over the subject matter and the parties in this matter have been performed or have occurred.
3. The Operator is in violation of Commission Statewide Rule 15 and did not timely request a hearing to contest the determination that it was in violation.
4. The Operator's P-5 Organization Report should not be renewed and all of the Operator's P-4 Certificates of Compliance should be cancelled, with all related pipeline or other carrier connections severed. 16 Tex. Admin. Code §3.15 (g)(4) and Tex. Nat. Res. Code §§89.022(f), 91.704 - 91.706.
5. The Operator's P-5 Organization Report cannot be renewed until the operator brings the inactive wells shown on the attached Exhibit A into compliance with the requirements of 16 Tex. Admin. Code §3.15 and Tex. Nat. Res. Code §§89.021 - 89.030.

IT IS ORDERED that renewal of Reneau Oil Co.'s P-5 Organization Report is hereby **DENIED**.

It is further ORDERED that all P-4 Certificates of Compliance issued to Reneau Oil Co. as operator of record are hereby **CANCELLED** and all related pipeline or other carrier connections are hereby **SEVERED**.

It is further ORDERED that Reneau Oil Co. shall bring the wells on Exhibit A into compliance with Statewide Rule 15 (16 TEX. ADMIN. CODE §3.15) and that the Operator's P-5 Organization Report shall not be renewed until the wells on Exhibit A have been brought into compliance as required by this order.

It is further ORDERED that Reneau Oil Co. and each person who held a position of ownership or control in the Operator at the time the Operator's most-recent P-5 Organization Report was filed shall be subject to the terms of TEX. NAT. RES. CODE §91.114.

It is further ORDERED by the Commission that this order shall not be final and effective until 25 days after the Commission's Order is signed, unless the time for filing a motion for rehearing has been extended under Tex. Gov't Code §2001.142, by agreement under Tex. Gov't Code §2001.147, or by written Commission Order issued pursuant to Tex. Gov't Code §2001.146(e). If a timely motion for rehearing is filed by any party at interest, this order shall not become final and effective until such motion is overruled, or if such motion is granted, this order shall be subject to further action by the Commission. Pursuant to Tex. Gov't Code §2001.146(e), the time allotted for Commission action on a motion for rehearing in this case prior to its being overruled by operation of law is hereby extended until 90 days from the date the Commission Order is signed.

All requested Findings of Fact and Conclusions of Law which are not expressly adopted herein are **DENIED**. All pending motions and request for relief not previously granted or granted herein are **DENIED**.

RAILROAD COMMISSION OF TEXAS

(Signatures affixed by Rule 15 Inactive Well
Master Order dated June 6, 2017.)

API Number	District	ID Number	Lease Name	Well Number
009 32160 No approved	09 W-3X on file	18239	CAMPBELL, R. ESTAE H	1
009 32161 No approved	09 W-3X on file	18239	CAMPBELL, R. ESTAE H	2
009 33190 No approved	09 W-3X on file	18008	CAMPBELL, ZINN	34
009 33191 No approved	09 W-3X on file	18239	CAMPBELL, R. ESTAE H	10
009 33317 No approved	09 W-3X on file	18239	CAMPBELL, R. ESTAE H	11
009 33715 No approved	09 W-3X on file	18008	CAMPBELL, ZINN	42
009 33823 No approved	09 W-3X on file	18008	CAMPBELL, ZINN	45
009 38404 No approved	09 W-3X on file	24829	CAMPBELL "C"	2
009 38405 No approved	09 W-3X on file	24829	CAMPBELL "C"	3
009 38779 No approved	09 W-3X on file	24829	CAMPBELL "C"	4
009 38906 No approved	09 W-3X on file	24829	CAMPBELL "C"	5
009 38981 No approved	09 W-3X on file	24829	CAMPBELL "C"	6
009 39196 No approved	09 W-3X on file	24829	CAMPBELL "C"	7
009 39329 No approved	09 W-3X on file	24829	CAMPBELL "C"	9
009 39330 No approved	09 W-3X on file	24829	CAMPBELL "C"	8
009 39466 No approved	09 W-3X on file	24829	CAMPBELL "C"	11
009 39722 No approved	09 W-3X on file	24829	CAMPBELL "C"	14
009 40512 No approved	09 W-3X on file	24829	CAMPBELL "C"	15
009 41636 No approved	09 W-3X on file	18008	CAMPBELL, ZINN	121

Docket No. 20-0305041

Exhibit A

API Number	District	ID Number	Lease Name	Well Number
009 41847 No approved W-3X on file	09	31108	ZINN CAMPBELL	5
009 42191 No approved W-3X on file	09	31823	CAMPBELL "M"	3
237 38624 No approved W-3X on file	09	03433	MOORE "B"	14
375 30087 No approved W-3X on file Must resolve Field Operations H-15 failure preventing 14(B)(2) approval	10	05919	MASTERSON "B"	1210
375 30150 No approved W-3X on file	10	05919	MASTERSON "B"	1209
375 30913 No approved W-3X on file	10	05305	BIVINS -PR-	3304
375 30942 No approved W-3X on file	10	05305	BIVINS -PR-	3144
375 30971 No approved W-3X on file	10	05305	BIVINS -PR-	2777
375 31047 No approved W-3X on file	10	05305	BIVINS -PR-	3135
375 31050 No approved W-3X on file	10	05305	BIVINS -PR-	3431
375 31053 No approved W-3X on file	10	05305	BIVINS -PR-	3413
375 31058 No approved W-3X on file	10	05305	BIVINS -PR-	3126
375 31091 No approved W-3X on file	10	05305	BIVINS -PR-	1753
375 31094 No approved W-3X on file	10	05305	BIVINS -PR-	3357
375 31100 No approved W-3X on file	10	05305	BIVINS -PR-	5508
375 31105 No approved W-3X on file	10	05305	BIVINS -PR-	857
375 31107 No approved W-3X on file	10	05305	BIVINS -PR-	2037
375 31125 No approved W-3X on file	10	05919	MASTERSON "B"	901

Docket No. 20-0305041

Exhibit A

API Number	District	ID Number	Lease Name	Well Number
375 31130	10	05919	MASTERSON "B"	1202
No approved W-3X on file				
Must resolve Field Operations H-15 failure preventing 14(B)(2) approval				
375 31135	10	05919	MASTERSON "B"	1205
No approved W-3X on file				
Must resolve Field Operations H-15 failure preventing 14(B)(2) approval				
483 30914	10	098945	KORBIN	1
No approved W-3X on file				
Must resolve Field Operations H-15 delinquency preventing 14B2 approval				
483 31033	10	101523	CHAD	1
No approved W-3X on file				
483 31065	10	104333	CLAIRE	1
No approved W-3X on file				
483 31110	10	109670	JAN	1
No approved W-3X on file				
483 31206	10	06907	LAYCOCK D	5
No approved W-3X on file				
483 31236	10	06907	LAYCOCK D	3
No approved W-3X on file				
483 31238	10	06907	LAYCOCK D	4
No approved W-3X on file				
503 82688	09	08657	VOGTSBERGER, R. C.	1
No approved W-3X on file				
503 82691	09	08657	VOGTSBERGER, R. C.	5
No approved W-3X on file				
503 82697	09	08691	ROENFELDT, W. A.	1
No approved W-3X on file				
503 82706	09	08738	VOGTSBERGER, R. C. -B-	3
No approved W-3X on file				

Docket No. 20-0305041

Exhibit A