RAILROAD COMMISSION OF TEXAS HEARINGS DIVISION

OIL & GAS DOCKET NO. 20-0294188

IN RE: P-5 ORGANIZATION REPORT OF SKYBRIDGE ENERGY LLC

FINAL ORDER

The Commission finds that after notice and an opportunity for hearing regarding the captioned matter, the Operator failed to request a hearing and pay the hearing fee as required by 16 Tex. ADMIN. CODE §3.15(g)(4) and Tex. Nat. Res. Code §89.022(f). This matter having been duly submitted to the Railroad Commission of Texas at conference held in its offices in Austin, Texas, the Commission makes the following findings of fact and conclusions of law.

FINDINGS OF FACT

- 1. Skybridge Energy LLC [Operator #786419] (the "Operator"), is the record operator or one or more inactive wells in the State of Texas and is required to file Organization Report (Form P-5) with the Commission. Operator's most recent P-5 was due on or before July 1, 2014.
- 2. After filing its most recent Organization Report (Form P-5) with the Commission, the Operator was notified they were deficient and had failed to comply with the requirements of 16 Tex. ADMIN. Code § 3.15 (Surface Equipment Removal Requirements and Inactive Wells) and provided with a written statement of the reasons for the determination and allowed ninety (90) days from the date its P-5 was due to comply with the requirements of 16 Tex. ADMIN. Code § 3.15 and Tex. Nat. Res. Code §§89.021 89.030.
- 3. After the expiration of ninety (90) days and pursuant to 16 Tex. ADMIN CODE §3.15(g)(4), an authorized Commission employee determined that the Operator's Organization Report still could not be renewed because the Operator continued to fail to comply with the requirements of 16 Tex. ADMIN. CODE §3.15 (Surface Equipment Removal Requirements and Inactive Wells).
- 4. The Commission sent the Operator a letter by certified mail giving notice to the Operator of the determination of continued non-compliance regarding specified inactive wells, attached as Exhibit A to this order, and advising the Operator of the right to request a hearing to show compliance. The letter notified the Operator that the hearing request must be received in docket services no later than 30 days after the date of the letter. The letter also notified the Operator that a final order denying renewal of the Operator's Organization Report (Form P-5) would result in the cancellation of all P-4 Certificates of Compliance and the severance of all pipeline or other carrier connections.

- 5. All notices and letters from the Commission to the Operator on this matter were addressed and mailed to the Operator's most recently reported address on the Form P-5 Organization Report.
- 6. The Operator did not timely request a hearing and pay the hearing fee on these issues as required under 16 Tex. Admin. Code §3.15(g)(4) (Surface Equipment Removal Requirements and Inactive Wells).
- 7. Statewide Rule 15 (16 Tex. ADMIN. CODE §3.15) is a Commission rule that relates to safety or the prevention or control of pollution.

CONCLUSIONS OF LAW

- 1. The Operator received proper notice and an opportunity for hearing regarding compliance with 16 Tex. Admin. Code §3.15 and Tex. Nat. Res. Code §§89.021 89.030.
- 2. All things necessary to the Commission attaining jurisdiction over the subject matter and the parties in this matter have been performed or have occurred.
- 3. The Operator is in violation of Commission Statewide Rule 15 and did not timely request a hearing to contest the determination that it was in violation.
- 4. The Operator's P-5 Organization Report should not be renewed and all of the Operator's P-4 Certificates of Compliance should be cancelled, with all related pipeline or other carrier connections severed. 16 Tex. Admin. Code §3.15 (g)(4) and Tex. Nat. Res. Code §§89.022(f), 91.704 91.706.
- 5. The Operator's P-5 Organization Report cannot be renewed until the operator brings the inactive wells shown on the attached Exhibit A into compliance with the requirements of 16 Tex. Admin. Code §3.15 and Tex. Nat. Res. Code §§89.021 89.030.

IT IS ORDERED that renewal of Skybridge Energy LLC's P-5 Organization Report is hereby **DENIED.**

It is further ORDERED that all P-4 Certificates of Compliance issued to Skybridge Energy LLC as operator of record are hereby CANCELLED and all related pipeline or other carrier connections are hereby SEVERED.

It is further ORDERED that Skybridge Energy LLC shall bring the wells on Exhibit A into compliance with Statewide Rule 15 (16 Tex. ADMIN. CODE §3.15) and that the Operator's P-5 Organization Report shall not be renewed until the wells on Exhibit A have been brought into compliance as required by this order.

It is further ORDERED that Skybridge Energy LLC and each person who held a position of ownership or control in the Operator at the time the Operator's most-recent P-5 Organization Report was filed shall be subject to the terms of Tex. Nat. Res. Code §91.114.

It is further ORDERED by the Commission that this order shall not be final and effective until 20 days after a party is notified of the Commission's order. A party is presumed to have been notified of the Commission's order three days after the date on which the notice is actually mailed. If a timely motion for rehearing is filed by any party at interest, this order shall not become final and effective until such motion is overruled, or if such motion is granted, this order shall be subject to further action by the Commission. Pursuant to Tex. Gov't. Code §2001.146(e), the time allotted for Commission action on a motion for rehearing in this case prior to its being overruled by operation of law, is hereby extended until 90 days from the date the parties are notified of the order.

All requested Findings of Fact and Conclusions of Law which are not expressly adopted herein are **DENIED**. All pending motions and request for relief not previously granted or granted herein are **DENIED**.

RAILROAD COMMISSION OF TEXAS

(Signatures affixed by Rule 15 Inactive Well Master Order dated December 9, 2014.)

1

API	Number Dia	strict	ID Number	Lease Name	Well Number
009	15146 No approved	09 W-3X on	11437 file	GARVEY -C-	2
009	16002 No approved			GARVEY -C-	1
009	84722 No approved	09 W-3X on	11437 file	GARVEY -C-	3
009	84723 No approved	09 W-3X on	11437 file	GARVEY -C-	3 R
009	84724 No approved	09 W-3X on	11437 file	GARVEY -C-	4
009	84725 No approved	W-3X on	file		6R
	Must resolve	e Field (perations H	-15 delinquency preventing 14B2 app	roval
093	31521 No approved			NEWMAN	1
143	00055 No approved	7B W-3X on	186682 file	COLLUM, ANNIE MAE	1
143	30513 No approved	7B W-3X on	088213 file	ROBINSON, T. C.	1
143	30588 No approved	7B W-3X on	088209 file	BROWN, T. W.	2
143	30631 No approved			RAMSEUR	1
143	30633 No approved	7B W-3X on	098458 file	GARY, S. E.	2
143	30664 No approved	7B W-3X on	090151 file	SIMMS	1
143	31034 No approved	7B W-3X on	29277 file	ROBINSON, T. C.	2
143	31047 No approved		22 4 517 file	GARY, S.E.	301
237	30116 No approved		16215 file	RUTH	1
	32561 No approved		16215 file	RUTH	2
237	35904 No approved		121740 file	RUTH	8

Docket No. 20-0294188

API	Number Di	strict	ID Number	Lease Name	Well Number
237	36550 No approved			RUTH	10
237	36689 No approved	09 W-3X on	121743 file	RUTH	11
363	32020 No approved	7B W-3X on	079845 file	BRANNON	1
363	32105 No approved	7B W-3X on	083614 file	BRANNON	2
363	32751 Electricity No approved	must be	097425 disconnected file	WELCH d (certify on Form W-3C)	1
363	35409 Electricity No approved	must be	212969 disconnected file	WELCH d (certify on Form W-3C)	2
363	35546 Electricity No approved	must be	221629 disconnected file	HILL d (certify on Form W-3C)	2
485	14461 No approved			BURNETT	37
485	15216 No approved	09 W-3X on	14850 file	BURNETT	B 13
485	15218 No approved	09 W-3X on	14850 file	BURNETT	16W
485	30624 No approved		13837 file	BURNETT -C-	4
	32739 No approved			BURNETT -D-	8
485	32741 No approved		14200 file	BURNETT -D-	6
	33240 No approved		14200 file	BURNETT -D-	14
485	33241 No approved	09 W-3X on	14850 file	BURNETT	34
	33242 No approved		14850 file	BURNETT	35
	33740 No approved		14850 file	BURNETT	38
485	33741 No approved	09 W-3X on	14200 file	BURNETT -D-	18

Docket No. 20-0294188

API	Number Dia	strict	ID Number	Lease Name	Well Number
485	34634 No approved	09 W-3X on	13837 file	BURNETT -C-	8
485	34635 No approved		13837 file	BURNETT -C-	7
485	36389 No approved		13837 file	BURNETT -C-	9
485	37915 No approved		14850 file	BURNETT	50
485	37916 No approved		14850 file	BURNETT	51
485	37917 No approved		14850 file	BURNETT	49
	No approved	W-3X on			2
485	No approved	W-3X on		BURNETT -C15 failure preventing 14(B)(2) ap	3 oproval
485		09	14200	_	2
485	90407 No approved	09 W-3X on	14200 file	BURNETT -D-	5
485	90409 No approved		14200 file	BURNETT -D-	10
485	90410 No approved	09 W-3X on	14200 file	BURNETT -D-	11
485	90411 No approved	09 W-3X on	14200 file	BURNETT -D-	12
485	90412 No approved		14200 file	BURNETT -D-	13
485	90413 No approved		14200 file	BURNETT -D-	15
485	90686 No approved		14850 file	BURNETT	3W
485	90699 No approved		14850 file	BURNETT	18
	90700 No approved		14850 file	BURNETT	19

Docket No. 20-0294188

API	Number Di	strict	ID Number	Lease Name	Well	Numbe
485	90701 No approved	_	14850 file	BURNETT		20
485	90708 No approved		14850 file	BURNETT		26
485	90709 No approved		14850 file	BURNETT		27
485	90714 No approved		14850 file	BURNETT		31
485	90715		14850	BURNETT		32

Docket No. 20-0294188