

**RAILROAD COMMISSION OF TEXAS  
HEARINGS DIVISION**

**OIL & GAS DOCKET NO. 20-0306536**

---

**IN RE: P-5 ORGANIZATION REPORT OF MAC 5 OPERATING, LLC**

---

**FINAL ORDER**

The Commission finds that after notice and an opportunity for hearing regarding the captioned matter, the Operator failed to request a hearing and pay the hearing fee as required by 16 TEX. ADMIN. CODE §3.15(g)(4) and TEX. NAT. RES. CODE §89.022(f). This matter having been duly submitted to the Railroad Commission of Texas at conference held in its offices in Austin, Texas, the Commission makes the following findings of fact and conclusions of law.

**FINDINGS OF FACT**

1. Mac 5 Operating, Llc [Operator #519562] (the “Operator”), is the record operator or one or more inactive wells in the State of Texas and is required to file Organization Report (Form P-5) with the Commission. Operator’s most recent P-5 was due on or before March 1, 2016.
2. After filing its most recent Organization Report (Form P-5) with the Commission, the Operator was notified they were deficient and had failed to comply with the requirements of 16 TEX. ADMIN. CODE § 3.15 (Surface Equipment Removal Requirements and Inactive Wells) and provided with a written statement of the reasons for the determination and allowed ninety (90) days from the date its P-5 was due to comply with the requirements of 16 TEX. ADMIN. CODE § 3.15 and TEX. NAT. RES. CODE §§89.021 - 89.030.
3. After the expiration of ninety (90) days and pursuant to 16 TEX. ADMIN CODE §3.15(g)(4), an authorized Commission employee determined that the Operator’s Organization Report still could not be renewed because the Operator continued to fail to comply with the requirements of 16 TEX. ADMIN. CODE §3.15 (Surface Equipment Removal Requirements and Inactive Wells).
4. The Commission sent the Operator a letter by certified mail giving notice to the Operator of the determination of continued non-compliance regarding specified inactive wells, attached as Exhibit A to this order, and advising the Operator of the right to request a hearing to show compliance. The letter notified the Operator that the hearing request must be received in docket services no later than 30 days after the date of the letter. The letter also notified the Operator that a final order denying renewal of the Operator’s Organization Report (Form P-5) would result in the cancellation of all P-4 Certificates of Compliance and the severance of all pipeline or other carrier connections.

5. All notices and letters from the Commission to the Operator on this matter were addressed and mailed to the Operator's most recently reported address on the Form P-5 Organization Report.
6. The Operator did not timely request a hearing and pay the hearing fee on these issues as required under 16 TEX. ADMIN. CODE §3.15(g)(4) (Surface Equipment Removal Requirements and Inactive Wells).
7. Statewide Rule 15 (16 TEX. ADMIN. CODE §3.15) is a Commission rule that relates to safety or the prevention or control of pollution.

### CONCLUSIONS OF LAW

1. The Operator received proper notice and an opportunity for hearing regarding compliance with 16 Tex. Admin. Code §3.15 and Tex. Nat. Res. Code §§89.021 - 89.030.
2. All things necessary to the Commission attaining jurisdiction over the subject matter and the parties in this matter have been performed or have occurred.
3. The Operator is in violation of Commission Statewide Rule 15 and did not timely request a hearing to contest the determination that it was in violation.
4. The Operator's P-5 Organization Report should not be renewed and all of the Operator's P-4 Certificates of Compliance should be cancelled, with all related pipeline or other carrier connections severed. 16 Tex. Admin. Code §3.15 (g)(4) and Tex. Nat. Res. Code §§89.022(f), 91.704 - 91.706.
5. The Operator's P-5 Organization Report cannot be renewed until the operator brings the inactive wells shown on the attached Exhibit A into compliance with the requirements of 16 Tex. Admin. Code §3.15 and Tex. Nat. Res. Code §§89.021 - 89.030.

**IT IS ORDERED** that renewal of Mac 5 Operating, Llc's P-5 Organization Report is hereby **DENIED**.

**It is further ORDERED** that all P-4 Certificates of Compliance issued to Mac 5 Operating, Llc as operator of record are hereby **CANCELLED** and all related pipeline or other carrier connections are hereby **SEVERED**.

**It is further ORDERED** that Mac 5 Operating, Llc shall bring the wells on Exhibit A into compliance with Statewide Rule 15 (16 TEX. ADMIN. CODE §3.15) and that the Operator's P-5 Organization Report shall not be renewed until the wells on Exhibit A have been brought into compliance as required by this order.

**It is further ORDERED** that Mac 5 Operating, Llc and each person who held a position of ownership or control in the Operator at the time the Operator's most-recent P-5 Organization Report was filed shall be subject to the terms of TEX. NAT. RES. CODE §91.114.

**It is further ORDERED** by the Commission that this order shall not be final and effective until 25 days after the Commission's Order is signed, unless the time for filing a motion for rehearing has been extended under Tex. Gov't Code §2001.142, by agreement under Tex. Gov't Code §2001.147, or by written Commission Order issued pursuant to Tex. Gov't Code §2001.146(e). If a timely motion for rehearing is filed by any party at interest, this order shall not become final and effective until such motion is overruled, or if such motion is granted, this order shall be subject to further action by the Commission. Pursuant to Tex. Gov't Code §2001.146(e), the time allotted for Commission action on a motion for rehearing in this case prior to its being overruled by operation of law is hereby extended until 90 days from the date the Commission Order is signed.

All requested Findings of Fact and Conclusions of Law which are not expressly adopted herein are **DENIED**. All pending motions and request for relief not previously granted or granted herein are **DENIED**.

**RAILROAD COMMISSION OF TEXAS**

(Signatures affixed by Rule 15 Inactive Well  
Master Order dated September 19, 2017.)

API Number	District	ID Number	Lease Name	Well Number
065 00039 No approved W-3X on file	10	06568	SCHAFFER RANCH EAST	244W
065 02828 No approved W-3X on file	10	06568	SCHAFFER RANCH EAST	49
065 02835 No approved W-3X on file	10	06568	SCHAFFER RANCH EAST	162W
065 02839 No approved W-3X on file	10	06568	SCHAFFER RANCH EAST	195W
065 02840 No approved W-3X on file	10	06568	SCHAFFER RANCH EAST	196W
065 02851 No approved W-3X on file	10	06568	SCHAFFER RANCH EAST	156W
065 02859 No approved W-3X on file	10	06568	SCHAFFER RANCH EAST	206W
065 02879 No approved W-3X on file	10	06568	SCHAFFER RANCH EAST	180W
065 02920 No approved W-3X on file	10	06568	SCHAFFER RANCH EAST	142
065 02929 No approved W-3X on file	10	06568	SCHAFFER RANCH EAST	165W
065 02932 No approved W-3X on file	10	06568	SCHAFFER RANCH EAST	171W
065 02937 No approved W-3X on file	10	06568	SCHAFFER RANCH EAST	202W
065 02938 No approved W-3X on file	10	06568	SCHAFFER RANCH EAST	208W
065 24260 No approved W-3X on file	10	06568	SCHAFFER RANCH EAST	264W
065 30013 Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file	10	00085	NOEL, J. L.	10
065 80016 Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file	10	023029	MCCONNELL	2
065 80506 No approved W-3X on file	10	025733	MCCONNELL	7
065 81463 No approved W-3X on file Must resolve UIC H-5 Test issue preventing 14(B)(2) approval	10	06568	SCHAFFER RANCH EAST	87W

Docket No. 20-0305536

Exhibit A

API Number	District	ID Number	Lease Name	Well Number
065 81523	10	06568	SCHAFFER RANCH EAST	176W
No approved W-3X on file				
065 81529	10	06568	SCHAFFER RANCH EAST	182W
No approved W-3X on file				
065 81549	10	06568	SCHAFFER RANCH EAST	203W
Surface equipment must be removed (certify on Form W-3C)				
No approved W-3X on file				
065 81581	10	06568	SCHAFFER RANCH EAST	240W
No approved W-3X on file				
179 06113	10	03061	PAMPA UNIT	B503
No approved W-3X on file				
179 06133	10	03061	PAMPA UNIT	A506
Electricity must be disconnected (certify on Form W-3C)				
No approved W-3X on file				
179 06163	10	03061	PAMPA UNIT	910
No approved W-3X on file				
179 06405	10	00606	SULLIVAN, R.	10W
No approved W-3X on file				
179 06544	10	03061	PAMPA UNIT	703
No approved W-3X on file				
179 06549	10	03061	PAMPA UNIT	708
No approved W-3X on file				
179 06644	10	03061	PAMPA UNIT	111G
No approved W-3X on file				
179 06766	10	06568	SCHAFFER RANCH EAST	69W
No approved W-3X on file				
179 06771	10	06568	SCHAFFER RANCH EAST	74W
No approved W-3X on file				
179 06776	10	06568	SCHAFFER RANCH EAST	80W
No approved W-3X on file				
179 06780	10	06568	SCHAFFER RANCH EAST	103W
No approved W-3X on file				
179 06783	10	06568	SCHAFFER RANCH EAST	106W
No approved W-3X on file				
179 06804	10	00350	CULLER	1
Electricity must be disconnected (certify on Form W-3C)				
No approved W-3X on file				
179 06805	10	00350	CULLER	2
Electricity must be disconnected (certify on Form W-3C)				
No approved W-3X on file				

Docket No. 20-0306536

Exhibit A

API Number	District	ID Number	Lease Name	Well Number
179 06808	10	00350	CULLER	5
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 06977	10	06568	SCHAFFER RANCH EAST	55W
No approved W-3X on file				
179 06978	10	06568	SCHAFFER RANCH EAST	56W
Surface equipment must be removed (certify on Form W-3C) No approved W-3X on file				
179 06981	10	06568	SCHAFFER RANCH EAST	59
No approved W-3X on file				
179 07001	10	00339	ARNOLD	3
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 07002	10	00339	ARNOLD	4
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 07003	10	00339	ARNOLD	5
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 07004	10	00339	ARNOLD	6
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 07015	10	00362	MORGAN	1
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 07016	10	00362	MORGAN	2
No approved W-3X on file				
179 07020	10	00362	MORGAN	6
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 07025	10	145554	MORGAN	11
No approved W-3X on file				
179 07037	10	06868	REST 80	6
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 07038	10	06868	REST 80	7
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 07042	10	00372	REST 160	11
No approved W-3X on file				

Docket No. 20-0306536

Exhibit A

API Number	District	ID Number	Lease Name	Well Number
179 07053	10	00372	REST 160	22G
No approved W-3X on file				
179 07087	10	00394	HARRAH	4
No approved W-3X on file				
179 07411	10	06568	SCHAFFER RANCH EAST	52W
Surface equipment must be removed (certify on Form W-3C)				
No approved W-3X on file				
179 07467	10	142719	PAMPA UNIT	C502G
No approved W-3X on file				
179 07608	10	00339	ARNOLD	2G
No approved W-3X on file				
179 07610	10	00339	ARNOLD	7G
No approved W-3X on file				
179 30674	10	04431	MCCONNELL "B"	1
No approved W-3X on file				
Must resolve Field Operations H-15 delinquency preventing 14B2 approval				
179 30802	10	03392	MCCONNELL "A" (GRYPHON)	2
No approved W-3X on file				
Must resolve Field Operations H-15 delinquency preventing 14B2 approval				
179 31072	10	134229	ZWEIG	5
No approved W-3X on file				
179 31629	10	06568	SCHAFFER RANCH EAST	286
No approved W-3X on file				
179 80685	10	026520	GLENN -B-	2
No approved W-3X on file				
179 81052	10	06568	SCHAFFER RANCH EAST	140W
No approved W-3X on file				
179 81142	10	00211	SMITH, ALEX	1
No approved W-3X on file				
179 81144	10	00211	SMITH, ALEX	3
No approved W-3X on file				
179 81145	10	00211	SMITH, ALEX	5
No approved W-3X on file				
179 81146	10	00211	SMITH, ALEX	6
No approved W-3X on file				
179 81147	10	00211	SMITH, ALEX	7
No approved W-3X on file				
179 81508	10	00297	HARRAH -A-	1
No approved W-3X on file				

Docket No. 20-0305536

Exhibit A

API Number	District	ID Number	Lease Name	Well Number
179 81510	10	00297	HARRAH -A-	3
No approved W-3X on file				
179 81512	10	00297	HARRAH -A-	5
No approved W-3X on file				
179 81513	10	00297	HARRAH -A-	6
No approved W-3X on file				
179 81516	10	00298	ARCHER	1
No approved W-3X on file				
179 81519	10	00298	ARCHER	4
No approved W-3X on file				
179 81525	10	00300	MCKINNEY	5
No approved W-3X on file				
179 81526	10	00300	MCKINNEY	6
No approved W-3X on file				
179 81527	10	00300	MCKINNEY	7
No approved W-3X on file				
179 81528	10	00300	MCKINNEY	8
No approved W-3X on file				
179 81529	10	00300	MCKINNEY	9
No approved W-3X on file				
179 81530	10	00300	MCKINNEY	10
No approved W-3X on file				
179 81531	10	00300	MCKINNEY	11
No approved W-3X on file				
179 81532	10	00300	MCKINNEY	12
No approved W-3X on file				
179 81535	10	00300	MCKINNEY	15
No approved W-3X on file				
179 81781	10	00339	ARNOLD	1
Electricity must be disconnected (certify on Form W-3C)				
No approved W-3X on file				
179 81788	10	00339	ARNOLD	8
Electricity must be disconnected (certify on Form W-3C)				
No approved W-3X on file				
179 81789	10	00339	ARNOLD	9
Electricity must be disconnected (certify on Form W-3C)				
No approved W-3X on file				
179 81790	10	00339	ARNOLD	10
Electricity must be disconnected (certify on Form W-3C)				
No approved W-3X on file				

Docket No. 20-0306536

# Exhibit A



API Number	District	ID Number	Lease Name	Well Number
179 81791	10	00339	ARNOLD	11
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 81792	10	00339	ARNOLD	12
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 81794	10	00339	ARNOLD	14
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 81795	10	00339	ARNOLD	15
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 81796	10	00339	ARNOLD	16
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 81828	10	00350	CULLER	6
No approved W-3X on file				
179 81844	10	00362	MORGAN	3
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 81845	10	00362	MORGAN	4
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 81846	10	00362	MORGAN	5
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 81849	10	00362	MORGAN	8
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 81851	10	00362	MORGAN	10
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 81853	10	00362	MORGAN	12
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 81854	10	00362	MORGAN	13
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 81855	10	00362	MORGAN	14
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				

Docket No. 20-0306536  
**Exhibit A**

API Number	District	ID Number	Lease Name	Well Number
179 81856	10	00362	MORGAN	15
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 81857	10	00362	MORGAN	16
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 81867	10	06868	REST 80	3
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 81868	10	06868	REST 80	4
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 81872	10	06868	REST 80	8
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 81877	10	06868	REST 80	13
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 82084	10	00394	HARRAH	2
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 82085	10	00394	HARRAH	3
No approved W-3X on file				
179 82088	10	00394	HARRAH	6
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 82090	10	00394	HARRAH	8
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 82096	10	00394	HARRAH	14
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 82097	10	00394	HARRAH	15
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 83071	10	00606	SULLIVAN, R.	4
No approved W-3X on file				
179 83072	10	00606	SULLIVAN, R.	5
No approved W-3X on file				
179 83077	10	00606	SULLIVAN, R.	12
No approved W-3X on file				

Docket No. 20-0306536

Exhibit A

API Number	District	ID Number	Lease Name	Well Number
179 83521	10	00659	MCKINNEY, D. F.	2
No approved W-3X on file				
179 83522	10	00659	MCKINNEY, D. F.	4
No approved W-3X on file				
179 83912	10	01540	HARRAH (GRYPHON)	1
No approved W-3X on file				
179 83913	10	01540	HARRAH (GRYPHON)	2
No approved W-3X on file				
Must resolve Field Operations H-15 delinquency preventing 14B2 approval				
179 84852	10	03061	PAMPA UNIT	103
No approved W-3X on file				
179 84853	10	03061	PAMPA UNIT	104
No approved W-3X on file				
179 84854	10	03061	PAMPA UNIT	105
No approved W-3X on file				
179 84856	10	03061	PAMPA UNIT	107
No approved W-3X on file				
179 84861	10	03061	PAMPA UNIT	112
No approved W-3X on file				
179 84862	10	03061	PAMPA UNIT	201
No approved W-3X on file				
179 84863	10	03061	PAMPA UNIT	202
No approved W-3X on file				
179 84864	10	03061	PAMPA UNIT	301
No approved W-3X on file				
179 84865	10	03061	PAMPA UNIT	302
No approved W-3X on file				
179 84866	10	03061	PAMPA UNIT	303G
No approved W-3X on file				
179 84868	10	03061	PAMPA UNIT	305
No approved W-3X on file				
179 84869	10	03061	PAMPA UNIT	306
No approved W-3X on file				
179 84873	10	03061	PAMPA UNIT	310
No approved W-3X on file				
179 84874	10	03061	PAMPA UNIT	311
No approved W-3X on file				

Docket No. 20-0306536

Exhibit A

API Number	District	ID Number	Lease Name	Well Number
179 84876	10	03061	PAMPA UNIT	313
No approved W-3X on file				
179 84880	10	03061	PAMPA UNIT	402
No approved W-3X on file				
179 84882	10	03061	PAMPA UNIT	404
No approved W-3X on file				
179 84894	10	03061	PAMPA UNIT	416
No approved W-3X on file				
179 84906	10	03061	PAMPA UNIT	A501
Electricity must be disconnected (certify on Form W-3C)				
No approved W-3X on file				
179 84907	10	03061	PAMPA UNIT	A502
Electricity must be disconnected (certify on Form W-3C)				
No approved W-3X on file				
179 84909	10	03061	PAMPA UNIT	A504
Electricity must be disconnected (certify on Form W-3C)				
No approved W-3X on file				
179 84910	10	03061	PAMPA UNIT	A505
Electricity must be disconnected (certify on Form W-3C)				
No approved W-3X on file				
179 84912	10	03061	PAMPA UNIT	A507
Electricity must be disconnected (certify on Form W-3C)				
No approved W-3X on file				
179 84913	10	03061	PAMPA UNIT	A508
Electricity must be disconnected (certify on Form W-3C)				
No approved W-3X on file				
179 84914	10	03061	PAMPA UNIT	A509
Electricity must be disconnected (certify on Form W-3C)				
No approved W-3X on file				
179 84915	10	03061	PAMPA UNIT	A510
Electricity must be disconnected (certify on Form W-3C)				
No approved W-3X on file				
179 84917	10	03061	PAMPA UNIT	B501
No approved W-3X on file				
179 84918	10	03061	PAMPA UNIT	B502
No approved W-3X on file				
179 84920	10	03061	PAMPA UNIT	B504
No approved W-3X on file				
179 84922	10	03061	PAMPA UNIT	B506
No approved W-3X on file				

Docket No. 20-0306536

Exhibit A

API Number	District	ID Number	Lease Name	Well Number
179 84923	10	03061	PAMPA UNIT	B507
No approved W-3X on file				
179 84928	10	03061	PAMPA UNIT	B512
No approved W-3X on file				
179 84929	10	03061	PAMPA UNIT	B513
No approved W-3X on file				
179 84933	10	03061	PAMPA UNIT	C503
No approved W-3X on file				
179 84935	10	03061	PAMPA UNIT	C505
No approved W-3X on file				
179 84981	10	03061	PAMPA UNIT	1801
No approved W-3X on file				
179 84982	10	03061	PAMPA UNIT	1802
No approved W-3X on file				
179 84983	10	03061	PAMPA UNIT	1901
No approved W-3X on file				
179 84989	10	03061	PAMPA UNIT	2003
Electricity must be disconnected (certify on Form W-3C)				
No approved W-3X on file				
179 84993	10	03061	PAMPA UNIT	6002
No approved W-3X on file				
179 84994	10	03061	PAMPA UNIT	6003
No approved W-3X on file				
179 84997	10	03061	PAMPA UNIT	7004
No approved W-3X on file				
179 84998	10	03061	PAMPA UNIT	7005
No approved W-3X on file				
179 85000	10	03061	PAMPA UNIT	7007
No approved W-3X on file				
179 85003	10	03061	PAMPA UNIT	7012
No approved W-3X on file				
179 85004	10	03061	PAMPA UNIT	7013
No approved W-3X on file				
179 85013	10	03061	PAMPA UNIT	8009
No approved W-3X on file				
179 85014	10	03061	PAMPA UNIT	8010
No approved W-3X on file				

Docket No. 20-0306536

Exhibit A

API Number	District	ID Number	Lease Name	Well Number
179 85016	10	03061	PAMPA UNIT	8012
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
179 85019	10	03061	PAMPA UNIT	9001
No approved W-3X on file				
179 85027	10	03061	PAMPA UNIT	9013
No approved W-3X on file				
179 85117	10	03392	MCCONNELL "A" (GRYPHON)	1
No approved W-3X on file				
179 85315	10	114697	ZWEIG	3
No approved W-3X on file				
179 85682	10	06568	SCHAFFER RANCH EAST	41
No approved W-3X on file				
179 85685	10	06568	SCHAFFER RANCH EAST	47
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
233 04410	10	01744	HUBER-PRITCHARD -A-	7
No approved W-3X on file				
233 20053	10	03534	HADLEY	103
No approved W-3X on file				
233 30099	10	051382	HADLEY	3
No approved W-3X on file				
233 30152	10	055258	MCNUTT	1016
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				
233 30173	10	053749	HADLEY	403
No approved W-3X on file				
233 30182	10	03534	HADLEY	703
No approved W-3X on file				
233 32526	10	149416	PRITCHARD	506
No approved W-3X on file				
233 32527	10	148046	MCCLOY	3067
No approved W-3X on file				
233 32711	10	163238	WOMBLE, R	4040
No approved W-3X on file				
233 32712	10	163290	WOMBLE, R	3040
No approved W-3X on file				
233 32761	10	169416	PRITCHARD	606
Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file				

Docket No. 20-0306536

Exhibit A

API Number	District	ID Number	Lease Name	Well Number
233 32817	10	171568	CUNNINGHAM	408
			Surface equipment must be removed (certify on Form W-3C) No approved W-3X on file	
233 32837	10	172210	PREALL	4065
			No approved W-3X on file	
233 80655	10	043057	PRITCHARD	1
			No approved W-3X on file	
233 84214	10	01590	HUBER-PRITCHARD	1W
			No approved W-3X on file	
233 84215	10	01590	HUBER-PRITCHARD	2
			No approved W-3X on file	
233 84216	10	01590	HUBER-PRITCHARD	3
			No approved W-3X on file	
233 84219	10	01590	HUBER-PRITCHARD	6
			No approved W-3X on file	
233 84221	10	01590	HUBER-PRITCHARD	8
			No approved W-3X on file	
233 84222	10	01590	HUBER-PRITCHARD	9
			Surface equipment must be removed (certify on Form W-3C) No approved W-3X on file	
341 30174	10	07025	BIVINS	3313
			No approved W-3X on file	
341 30203	10	07025	BIVINS	3316
			No approved W-3X on file	
341 81027	10	025685	BEARD	5
			No approved W-3X on file	

Docket No. 20-0306536

**Exhibit A**