RAILROAD COMMISSION OF TEXAS HEARINGS DIVISION

OIL & GAS DOCKET NO. 20-0309022

IN RE: P-5 ORGANIZATION REPORT OF MYERS, JAMES B.

FINAL ORDER

The Commission finds that after notice and an opportunity for hearing regarding the captioned matter, the Operator failed to request a hearing and pay the hearing fee as required by 16 Tex. ADMIN. CODE §3.15(g)(4) and Tex. NAT. Res. CODE §89.022(f). This matter having been duly submitted to the Railroad Commission of Texas at conference held in its offices in Austin, Texas, the Commission makes the following findings of fact and conclusions of law.

FINDINGS OF FACT

- 1. Myers, James B. [Operator #597665] (the "Operator"), is the record operator or one or more inactive wells in the State of Texas and is required to file Organization Report (Form P-5) with the Commission. Operator's most recent P-5 was due on or before August 1, 2016.
- 2. After filing its most recent Organization Report (Form P-5) with the Commission, the Operator was notified they were deficient and had failed to comply with the requirements of 16 Tex. ADMIN. Code § 3.15 (Surface Equipment Removal Requirements and Inactive Wells) and provided with a written statement of the reasons for the determination and allowed ninety (90) days from the date its P-5 was due to comply with the requirements of 16 Tex. ADMIN. Code § 3.15 and Tex. Nat. Res. Code §§89.021 89.030.
- 3. After the expiration of ninety (90) days and pursuant to 16 Tex. ADMIN CODE §3.15(g)(4), an authorized Commission employee determined that the Operator's Organization Report still could not be renewed because the Operator continued to fail to comply with the requirements of 16 Tex. ADMIN. CODE §3.15 (Surface Equipment Removal Requirements and Inactive Wells).
- 4. The Commission sent the Operator a letter by certified mail giving notice to the Operator of the determination of continued non-compliance regarding specified inactive wells, attached as Exhibit A to this order, and advising the Operator of the right to request a hearing to show compliance. The letter notified the Operator that the hearing request must be received in docket services no later than 30 days after the date of the letter. The letter also notified the Operator that a final order denying renewal of the Operator's Organization Report (Form P-5) would result in the cancellation of all P-4 Certificates of Compliance and the severance of all pipeline or other carrier connections.

- 5. All notices and letters from the Commission to the Operator on this matter were addressed and mailed to the Operator's most recently reported address on the Form P-5 Organization Report.
- 6. The Operator did not timely request a hearing and pay the hearing fee on these issues as required under 16 Tex. Admin. Code §3.15(g)(4) (Surface Equipment Removal Requirements and Inactive Wells).
- 7. Statewide Rule 15 (16 TEX. ADMIN. CODE §3.15) is a Commission rule that relates to safety or the prevention or control of pollution.

CONCLUSIONS OF LAW

- 1. The Operator received proper notice and an opportunity for hearing regarding compliance with 16 Tex. Admin. Code §3.15 and Tex. Nat. Res. Code §§89.021 89.030.
- 2. All things necessary to the Commission attaining jurisdiction over the subject matter and the parties in this matter have been performed or have occurred.
- 3. The Operator is in violation of Commission Statewide Rule 15 and did not timely request a hearing to contest the determination that it was in violation.
- 4. The Operator's P-5 Organization Report should not be renewed and all of the Operator's P-4 Certificates of Compliance should be cancelled, with all related pipeline or other carrier connections severed. 16 Tex. Admin. Code §3.15 (g)(4) and Tex. Nat. Res. Code §§89.022(f), 91.704 91.706.
- 5. The Operator's P-5 Organization Report cannot be renewed until the operator brings the inactive wells shown on the attached Exhibit A into compliance with the requirements of 16 Tex. Admin. Code §3.15 and Tex. Nat. Res. Code §§89.021 89.030.

IT IS ORDERED that renewal of Myers, James B.'s P-5 Organization Report is hereby **DENIED**.

It is further ORDERED that all P-4 Certificates of Compliance issued to Myers, James B. as operator of record are hereby CANCELLED and all related pipeline or other carrier connections are hereby SEVERED.

It is further ORDERED that Myers, James B. shall bring the wells on Exhibit A into compliance with Statewide Rule 15 (16 TEX. ADMIN. CODE §3.15) and that the Operator's P-5 Organization Report shall not be renewed until the wells on Exhibit A have been brought into compliance as required by this order.

It is further ORDERED that Myers, James B. and each person who held a position of ownership or control in the Operator at the time the Operator's most-recent P-5 Organization Report was filed shall be subject to the terms of Tex. Nat. Res. Code §91.114.

It is further ORDERED by the Commission that this order shall not be final and effective until 25 days after the Commission's Order is signed, unless the time for filing a motion for rehearing has been extended under Tex. Gov't Code §2001.142, by agreement under Tex. Gov't Code §2001.147, or by written Commission Order issued pursuant to Tex. Gov't Code §2001.146(e). If a timely motion for rehearing is filed by any party at interest, this order shall not become final and effective until such motion is overruled, or if such motion is granted, this order shall be subject to further action by the Commission. Pursuant to Tex. Gov't Code §2001.146(e), the time allotted for Commission action on a motion for rehearing in this case prior to its being overruled by operation of law is hereby extended until 90 days from the date the Commission Order is signed.

All requested Findings of Fact and Conclusions of Law which are not expressly adopted herein are **DENIED**. All pending motions and request for relief not previously granted or granted herein are **DENIED**.

RAILROAD COMMISSION OF TEXAS

(Signatures affixed by Rule 15 Inactive Well Master Order dated February 13, 2018.)

API	Number Di	strict	ID Number	Lease Name	Well	Numbe
009	03471 No approved			CAMPBELL BANKING COMPANY		3
009	07950 No approved			GOLDSMITH, N. D.		5
009	19325 No approved			CAMPBELL BANKING COMPANY		4
009	19327 No approved		00383 file	ECHOLS -B-		1
009	19328 No approved		00383 file	ECHOLS -B-		2
009	19331 No approved		00383 file	ECHOLS -B-		6
009	19334 No approved		00383 file	ECHOLS -B-		9
009	31121 No approved			GOLDSMITH, N. D.	//8/	23
009	31386 No approved			SCRUGGS, LOIS		1
009	31673 No approved		17896 file	SCRUGGS, LOIS -B-		1
009	32334 No approved			PORTWOOD -C- & -D-		29
009	32896 No approved			GOLDSMITH, N. D.		24
009	32901 No approved			HARGRAVES "F"		2
009	33538 No approved			CAMPBELL BANKING CO.		11
009	33539 No approved			CAMPBELL BANKING CO.		12
009	34558 No approved			CAMPBELL BANKING CO.		13
009	35217 No approved			PORTWOOD -C- & -D-		30
009	38819 No approved			YORK, B. H. EST.		7
009	39756 No approved			ROBY-CHEATHAM UNIT		1

Docket No. 20-0309022

Exhibit A

Page: :

Docket No. 20-0309022

No approved W-3X on file

Exhibit A

Well Number API Number District ID Number Lease Name 5 01365 PORTWOOD -D-09 023 80038 No approved W-3X on file 01365 PORTWOOD -D-18 023 80042 09 No approved W-3X on file 35 503 37795 09 07237 DEITRICH -B-Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file CAMPBELL, R., ESTATE -E-1WS 503 80309 09 07110 Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file CAMPBELL, R., ESTATE -E-503 80310 09 07110 Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file CAMPBELL, R., ESTATE -E-6 503 80315 09 07110 Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file 18 CAMPBELL, R., ESTATE -E-07110 503 80324 09 Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file 07110 CAMPBELL, R., ESTATE -E-19 503 80325 09 Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file CAMPBELL, R., ESTATE -E-20 503 80326 09 07110 Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file DEITRICH -B-6 07237 503 80690 09 Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file 9 DEITRICH -B-07237 503 80691 Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file Must resolve Field Operations H-15 delinquency preventing 14B2 approval DEITRICH -B-16 09 07237 503 80695 Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file 09 07237 DEITRICH -B-25 503 80700 Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file DEITRICH -B-28 07237 503 80703 09 Electricity must be disconnected (certify on Form W-3C)

Page:

Docket No. 20-0309022

No approved W-3X on file

Exhibit A

No approved W-3X on file

Well Number API Number District ID Number Lease Name 07237 DEITRICH -B-30 09 503 80704 Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file 19 07287 GASS, HARRIET M., EST. 503 80857 09 Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file 2 07313 DEITRICH 503 80955 09 No approved W-3X on file 3 CAMPBELL, R., ESTATE -E-07110 09 Electricity must be disconnected (certify on Form W-3C) No approved W-3X on file CAMPBELL, R., ESTATE -E-16 07110 503 81821 Electricity must be disconnected (certify on Form W-3C)

Page: 4

Docket No. 20-0309021. Exhibit A