

**RAILROAD COMMISSION OF TEXAS
HEARINGS DIVISION**

OIL AND GAS DOCKET NO. 01-0309655

ENFORCEMENT ACTION AGAINST HIGHER STANDARD OIL COMPANY, INC. (OPERATOR NO. 385715) FOR VIOLATIONS OF STATEWIDE RULES ON THE ALEXANDER "B" (11349) LEASE, WELL NO. 3, PLUM CREEK, N. (DALE LIME) FIELD, CALDWELL COUNTY; AND E. F. JOHNSON (17548) LEASE, WELL NO. 3, WILDCAT FIELD, COUNTY, TEXAS

FINAL ORDER

The Railroad Commission of Texas ("Commission") finds that after statutory notice the captioned enforcement proceeding was heard by a Commission Administrative Law Judge on September 13, 2018, and that the respondent, Higher Standard Oil Company, Inc., failed to appear or respond to the Notice of Opportunity for Hearing. Pursuant to § 1.25 of the Commission's General Rules of Practice and Procedure, 16 TEX. ADMIN. CODE § 1.25, and after being duly submitted to the Commission at a conference held in its offices in Austin, Texas, the Commission makes the following findings of fact and conclusions of law.

FINDINGS OF FACT

1. Higher Standard Oil Company, Inc. ("Respondent"), Operator No. 385715, was sent the Original Complaint and Notice of Opportunity for Hearing by certified and first-class mail, addressed to the most recent Commission Form P-5 (Organization Report) ("Form P-5") address. Respondent's officer as identified on the Form P-5—Geary Trigleth—was sent the Original Complaint and Notice of Opportunity for Hearing by certified and first-class mail, addressed to the last known address.
2. The certified mail envelope containing the Original Complaint and Notice of Opportunity for Hearing addressed to the Respondent was received on August 3, 2018. The first-class mail was not returned. Record of the delivery and return of certified mail has been on file with the Commission for more than 15 days, exclusive of the day of receipt and day of issuance. Respondent was given more than 30 days' notice of the Original Complaint and Notice of Opportunity for Hearing. Respondent has not entered into an agreed settlement order, filed an answer or requested a hearing.
3. On April 17, 2017, Respondent, a corporation, filed a Form P-5 with the Commission reporting that its officer consists of the following individual: Geary Trigleth, President/Secretary.
4. Geary Trigleth was in a position of ownership or control of Respondent, as defined in TEX. NAT. RES. CODE § 91.114, during the time period of the violations of Commission rules committed by Respondent.

5. Respondent's Form P-5 is delinquent. Respondent had a \$50,000.00 cash deposit as its financial assurance at the time of the last Form P-5 annual renewal submission.
6. Respondent designated itself to the Commission as the operator of the Alexander "B" (11349) Lease, Well No. 3, by filing a Commission Form P-4 (Certificate of Compliance and Transportation Authority), effective January 30, 2017, approved April 18, 2017.
7. Respondent designated itself to the Commission as the operator of the E. F. Johnson (17548) Lease, Well No. 3, by filing a Commission Form P-4 (Certificate of Compliance and Transportation Authority), effective May 1, 2013, approved June 4, 2014.
8. Commission inspection reports made on September 26, 2017, December 4, 2017 and February 23, 2018 for the Alexander "B" (11349) Lease show that the signs or identification required to be posted at the lease entrance was missing.
9. Commission inspection reports made on July 24, 2015, July 30, 2015, October 8, 2015, January 28, 2016, January 4, 2017, February 13, 2017, March 8, 2017, September 25, 2017, November 16, 2017, February 8, 2018, and June 14, 2018 for the E. F. Johnson (17548) Lease show that the signs or identification required to be posted at the lease entrance was missing.
10. Commission inspection reports made on December 4, 2017 and February 23, 2018 for the Alexander "B" (11349) Lease, Well No. 3 shows that the sign or identification required to be posted at the well location was missing.
11. Commission inspection reports made on July 13, 2015, July 24, 2015, July 30, 2015, October 8, 2015, January 28, 2016, January 4, 2017, February 13, 2017, March 8, 2017, September 25, 2017, November 16, 2017, February 8, 2018, and June 14, 2018 for the E. F. Johnson (17548) Lease, Well No. 3 shows that the sign or identification required to be posted at the well location was missing.
12. Commission inspection reports made on December 4, 2017 and February 23, 2018 for the Alexander "B" (11349) Lease show that the signs or identification required to be posted at the tank battery was missing.
13. The lack of legible signs and identification displaying correct information, as set forth in Statewide Rules 3(1), 3(2), 3(3), may cause confusion as to the responsible operator to be contacted and the actual location of a violation or emergency, which can result in delays in remedying a violation or emergency.
14. Commission inspection reports made on October 18, 2017 and February 23, 2018, and the absence of reported production since May 2014, showed that the Alexander "B" (11349) Lease, Well No. 3 has been inactive for a period greater than one year. Production from the subject lease ceased on or before June 2014.
15. Commission inspection reports made on January 20, 2017, October 18, 2017, and January 22, 2018, and the absence of reported production since April 2012,

showed that the E. F. Johnson (17548) Lease, Well No. 3 has been inactive for a period greater than one year. Production from the subject lease ceased on or before May 2012.

16. No workovers, re-entries, or subsequent operations have taken place on the subject well within the last twelve months; the subject well has not been properly plugged in accordance with Statewide Rule 14, 16 TEX. ADMIN CODE § 3.14; and no plugging extensions are in effect for the subject well as allowed by Statewide Rule 14.
17. Usable quality groundwater in the area can become contaminated by migrations or discharges of saltwater and other oil and gas waste from the subject well. Unplugged wellbores, in violation of Statewide Rule 14(b)(2), constitute a cognizable threat to the public health and safety because of the potential of pollution.
18. The total estimated cost to the State for plugging the Alexander "B" (11349) Lease Well No. 3 is \$13,067.25. The total estimated cost to the State for plugging the E. F. Johnson (17548) Lease Well No. 3 is \$24,325.70.
19. Commission inspection reports made on January 20, 2017, and October 18, 2017, show Respondent was using and maintaining unauthorized waste pits.
20. Continued maintenance of unpermitted pits, in violation of Statewide Rule 8(d)(2), may result in unpermitted discharges of oil and gas waste which can contaminate the land surface, affect the health of humans and animals, and may be discharged to surface or subsurface waters, causing pollution.
21. The Respondent has no prior history of violations of Commission Rules.

CONCLUSIONS OF LAW

1. Proper notice was issued by the Commission to Respondent and all other appropriate persons legally entitled to notice.
2. All things necessary to the Commission attaining jurisdiction over the subject matter and the parties have been performed or have occurred.
3. Respondent is responsible for maintaining the subject lease in compliance with all applicable Commission rules and TEX. NAT. RES. CODE, chs. 89 and 91.
4. Respondent is in violation of Statewide Rules 3(1), 3(2), 3(3), 14(b)(2), and 8(2). 16 TEX. ADMIN. CODE §§ 3.3(1), 3.3(2), 3.3(3), 3.14(b)(2), and 3.8(2).
5. The documented violations committed by Respondent constitute acts deemed serious, and a hazard to the public health, and demonstrate a lack of good faith pursuant to TEX. NAT. RES. CODE § 81.0531(c).

6. Respondent is responsible for maintaining the subject leases in compliance with Statewide Rule 3(1), which requires that each well site that produces oil, gas, or geothermal resources shall post signs or identification showing the name of the property, name of the operator and the well number.
7. Respondent is responsible for maintaining the subject leases in compliance with Statewide Rule 3(2), which requires that each well site that produces oil, gas, or geothermal resources shall post signs or identification showing the name of the property, name of the operator and the well number.
8. Respondent is responsible for maintaining the subject leases in compliance with Statewide Rule 3(3), which requires that each tank battery that produces oil, gas, or geothermal resources shall post signs or identification showing the name of the property, commission lease number, name of the operator, number of acres in the property and if commingled, include the commingling permit number.
9. Respondent is responsible for maintaining the subject leases in compliance with Statewide Rule 14(b)(2), which requires that plugging operations on each dry or inactive well shall be commenced within a period of one year after drilling or operations cease and shall proceed with due diligence until completed, unless the operator is eligible for and obtains an extension of the plugging deadline.
10. Respondent is responsible for maintaining the subject lease in compliance with Statewide Rule 8(d)(2), which requires that pits not otherwise authorized by rule, be permitted.
11. Pursuant to TEX. NAT. RES. CODE § 81.0531, the Commission may assess administrative penalties against Respondent for the subject violations of up to \$10,000 per day for each violation, with each day such violations continued constituting a separate violation.
12. An assessed administrative penalty in the amount of **SEVENTEEN THOUSAND, ONE HUNDRED NINETY-TWO DOLLARS (\$17,192.00)** is justified considering the facts and violations at issue.
13. As a person in a position of ownership or control of Respondent at the time Respondent violated Commission rules related to safety and the control of pollution, Geary Tringleth, and any other organization in which this individual may hold a position of ownership or control, is subject to the restriction in TEX. NAT. RES. CODE § 91.114(a)(2).

ORDERING PROVISIONS

IT IS ORDERED THAT within 30 days from the day immediately following the date this order becomes final:

1. Higher Standard Oil Company, Inc. (Operator No. 385715) shall plug the Alexander "B" (11349) Lease, Well No. 3; and E. F. Johnson (17548) Lease, Well No. 3, and place the subject leases in compliance with Statewide Rules 3(1), 3(2), 3(3), 14(b)(2), and 8(2), and any other applicable Commission rules and statutes.
2. Higher Standard Oil Company, Inc. (Operator No. 385715) shall pay to the Railroad Commission of Texas, for disposition as provided by law, an administrative penalty in the amount of **SEVENTEEN THOUSAND, ONE HUNDRED NINETY-TWO DOLLARS (\$17,192.00)**.

It is further **ORDERED** that as a person in a position of ownership or control of Respondent at the time Respondent violated Commission rules related to safety and the control of pollution, Geary Trigleth, and any other organization in which this individual may hold a position of ownership or control, **shall be subject to the restriction in TEX. NAT. RES. CODE § 91.114(a)(2) for a period of no more than seven years from the date the order entered in this matter becomes final**, or until the conditions that constituted the violations herein are corrected or are being corrected in accordance with a schedule to which the Commission and the organization have agreed, and all administrative, civil, and criminal penalties and all cleanup and plugging costs incurred by the State relating to those conditions are paid or are being paid in accordance with a schedule to which the Commission and the organization have agreed.

It is further **ORDERED** by the Commission that this order shall not be final and effective until 25 days after the order is signed, unless the time for filing a motion for rehearing has been extended under TEX. GOV'T CODE § 2001.142, by agreement under TEX. GOV'T CODE § 2001.147, or by written Commission order issued pursuant to TEX. GOV'T CODE § 2001.146(e). If a timely motion for rehearing of an application is filed by any party at interest, this order shall not become final and effective until such motion is overruled, or if such motion is granted, this order shall be subject to further action by the Commission. Pursuant to TEX. GOV'T CODE § 2001.146(e), the time allotted for Commission action on a motion for rehearing in this case prior to its being overruled by operation of law is hereby extended until 100 days from the date the Commission order is signed.

All requested findings of fact and conclusions of law, which are not expressly adopted herein, are denied. All pending motions and requests for relief not previously granted or granted herein are denied.

Noncompliance with the provisions of this order is subject to enforcement by the Attorney General and subject to civil penalties of up to \$10,000 per day per violation.

Done this 30th day of October 2018.

RAILROAD COMMISSION OF TEXAS

(Signatures affixed by Default Master
Order dated October 30, 2018)