# RAILROAD COMMISSION OF TEXAS OFFICE OF GENERAL COUNSEL

# OIL AND GAS DOCKET NO. 09-0319996

ENFORCEMENT ACTION AGAINST NORTEX PRODUCTION CO., LLC (OPERATOR NO. 613562) FOR VIOLATIONS OF STATEWIDE RULES ON THE FOSTER (30716) LEASE, WELL NOS. 1B, 2, 3, 6, 15, 16, 20, AND 21, WICHITA COUNTY REGULAR FIELD, WICHITA COUNTY, TEXAS

## FINAL ORDER

The Railroad Commission of Texas ("Commission") finds that statutory notice of the captioned enforcement proceeding was provided pursuant to Commission rules, and that the Respondent, Nortex Production Co., LLC, failed to appear or respond to the **Notice of Opportunity for Hearing**. Pursuant to § 1.25 of the Commission's General Rules of Practice and Procedure, 16 Texas Administrative Code § 1.25, and after being duly submitted to the Commission at a Conference held in its offices in Austin, Texas, the Commission makes the following findings of fact and conclusions of law.

## FINDINGS OF FACT

- 1. Nortex Production Co., LLC ("Respondent"), Operator No. 613562, was sent the Original Complaint and Notice of Opportunity for Hearing by certified and first-class mail, addressed to the most recent Commission Form P-5 (Organization Report) ("Form P-5") address.
- 2. The certified mail envelope containing the Original Complaint and Notice of Opportunity for Hearing addressed to the Respondent was received on September 13, 2019. The first-class mail was not returned. Record of the delivery and return of certified mail has been on file with the Commission for more than 15 days, exclusive of the day of receipt and day of issuance. Respondent was given more than 30 days' notice of the Original Complaint and Notice of Opportunity for Hearing. Respondent has not entered into an agreed settlement order, filed an answer or requested a hearing.
- 3. On January 5, 2017, Respondent, a limited liability company, filed a Form P-5 with the Commission reporting that its officer consists of the following individual: Mark Papak, Member.
- 4. Respondent's Form P-5 is delinquent. Respondent had a \$50,000.00 letter of credit as its financial assurance at the time of the last Form P-5 annual renewal submission.
- 5. Respondent designated itself to the Commission as the operator of the Foster (30716) Lease, Well Nos. 1B, 2, 3, 6, 15, 16, 20, and 21, by filing a Commission Form P-4 (Certificate of Compliance and Transportation Authority), effective March 25, 2010, approved April 8, 2010.
- 6. Commission inspection reports made on October 3, 2018, October 16, 2018, February 25, 2019, April 12, 2019 and September 12, 2019 for the Foster (30716) Lease show that the sign

or identification required to be posted at each well location displays the incorrect operator name at Well No. 16.

- 7. The lack of a legible sign and identification displaying correct information, as set forth in Statewide Rule 3(2), may cause confusion as to the responsible operator to be contacted and the actual location of a violation or emergency, which can result in delays in remedying a violation or emergency.
- 8. Commission district inspection reports made on October 3, 2018, October 16, 2018, February 25, 2019, April 12, 2019 and September 12, 2019 for the Foster (30716) Lease show that Well No. 21 is open to the atmosphere.
- 9. Wells left uncontrolled or open to the atmosphere, in violation of Statewide Rule 13(a)(6)(A), may discharge oil and gas waste onto the land surface and affect the health of humans and animals; these discharges may eventually make their way to surface or subsurface waters, causing pollution.
- 10. Well Nos. 2 and 16 of the Foster (30716) Lease are permitted injection wells. Commission District inspection reports made on October 3, 2018, October 16, 2018, February 25, 2019, April 12, 2019 and September 12, 2019, and the absence of reported production since June 2016 and the absence of reported injection since June 2000 for Well No. 2 and June 2017 for Well No. 16, show that the Foster (30716) Lease, Well Nos. 1B, 2, 3, 6, 15, 16, and 21, have been inactive for a period greater than one year. Production from Well Nos. 1B, 3, 6, 15 and 21 ceased in May 2016. Injection into Well No. 2 ceased in May 2000 and injection into Well No. 16 ceased in May 2017.
- 11. No workovers, re-entries, or subsequent operations have taken place on the subject wells within the last twelve months and the subject wells have not been properly plugged in accordance with Statewide Rule 14. 16 Tex. Admin. Code § 3.14. No plugging extensions are in effect for the subject wells as allowed by Statewide Rule 14.
- 12. Usable quality groundwater in the area can become contaminated by migrations or discharges of saltwater and other oil and gas waste from the subject well. Unplugged wellbores, in violation of Statewide Rule 14(b)(2), constitute a cognizable threat to the public health and safety because of the potential of pollution.
- 13. Well No. 16 of the Foster (30716) Lease is a permitted injection well. According to Commission records, the subject well was due for a disposal/injection well pressure test on October 30, 2017. Commission records show Respondent has failed to pressure test the well.
- 14. Disposal/injection wells must pass a pressure test at least once every five years, or as required by permit, to show that the well is not leaking, the at waste is being confined to the permitted injection interval, and that the usable quality water zones are properly isolated. Any injection of fluid down a wellbore could be a potential source of pollution. Without testing and supporting documentation, as required by Statewide Rule 46(j), the Commission cannot determine if a well poses a threat to natural resources.
- 15. The total estimated cost to the State for plugging the Foster (30716) Lease Well Nos. 1B, 2, 3, 6, 15, 16, 20, and 21 is \$36,400.00.
- 16. Respondent has no prior history of violations of Commission Rules.

### **CONCLUSIONS OF LAW**

- 1. Proper notice was issued by the Commission to Respondent and all other appropriate persons legally entitled to notice.
- 2. All things necessary to the Commission attaining jurisdiction over the subject matter and the parties have been performed or have occurred.
- 3. Respondent is responsible for maintaining the subject lease in compliance with all applicable Commission rules and Texas Natural Resources Code, Chapters 89 and 91.
- 4. Respondent is in violation of Statewide Rules 3(2), 13(a)(6)(A), 14(b)(2), and 46(j). 16 Tex. Admin. Code §§ 3.3(2), 3.13(a)(6)(A), 3.14(b)(2), and 3.46(j).
- 5. The documented violations committed by Respondent constitute acts deemed serious, and a hazard to the public health, and demonstrate a lack of good faith pursuant to Texas Natural Resources Code § 81.0531(c).
- 6. Respondent is responsible for maintaining the subject lease in compliance with Statewide Rule 3(2), which requires that each well site that produces oil, gas, or geothermal resources shall post signs or identification showing the name of the property, name of the operator and the well number.
- Respondent is responsible for maintaining surface control of a well by using wellhead assemblies in compliance with Statewide Rule 13(a)(6)(A). Maintenance of surface control is necessary not only to prevent fluids from being discharged from the wellbore onto the ground surface, but also to prevent any oil and gas wastes present in the wellbore from being displaced to surface by influxes of surface water into the open wellbore.
- 8. Respondent is responsible for maintaining the subject leases in compliance with Statewide Rule 14(b)(2), which requires that plugging operations on each dry or inactive well shall be commenced within a period of one year after drilling or operations cease and shall proceed with due diligence until completed, unless the operator is eligible for and obtains an extension of the plugging deadline.
- 9. Respondent is responsible for maintaining the subject lease in compliance with Statewide Rule 46(j), which requires a passing mechanical integrity test every five years.
- 10. Pursuant to Texas Natural Resources Code § 81.0531, the Commission may assess administrative penalties against Respondent for the subject violations of up to \$10,000 per day for each violation, with each day such violations continued constituting a separate violation.

- 11. An assessed administrative penalty in the amount of THIRTY-THREE THOUSAND FOUR HUNDRED EIGHTY DOLLARS (\$33,480.00) is justified considering the facts and violations at issue.
- 12. Respondent violated Commission rules related to safety and the control of pollution. Any other organization in which an officer of this organization holds a position of ownership or control, is subject to the restriction in Texas Natural Resources Code § 91.114.

#### ORDERING PROVISIONS

IT IS ORDERED THAT within 30 days from the day immediately following the date this order becomes final:

- 1. Nortex Production Co., LLC (Operator No. 613562) shall PLUG the Foster (30716) Lease, Well Nos. 1B, 2, 3, 6, 15, 16, 20, and 21 in accordance with Statewide Rule14(b)(2) and shall place the subject lease and wells into compliance with Statewide Rules 3(2), 13(a)(6)(A), and 46(j), and any other applicable Commission rules and statutes.
- 2. Nortex Production Co., LLC (Operator No. 613562) shall pay to the Railroad Commission of Texas, for disposition as provided by law, an administrative penalty in the amount of THIRTY-THREE THOUSAND FOUR HUNDRED EIGHTY DOLLARS (\$33,480.00).

It is further **ORDERED** by the Commission that this order shall not be final and effective until 25 days after the order is signed, unless the time for filing a motion for rehearing has been extended under Texas Government Code § 2001.142, by agreement under Texas Government Code § 2001.147, or by written Commission order issued pursuant to Texas Government Code § 2001.146(e). If a timely motion for rehearing of an application is filed by any party at interest, this order shall not become final and effective until such motion is overruled, or if such motion is granted, this order shall be subject to further action by the Commission. Pursuant to Texas Government Code § 2001.146(e), the time allotted for Commission action on a motion for rehearing in this case prior to its being overruled by operation of law is hereby extended until 100 days from the date the Commission order is signed.

Any other organization in which an officer of this organization holds a position of ownership or control at the time Respondent violated Commission rules related to safety and the control of pollution, shall be subject to the restriction in Texas Natural Resources Code § 91.114(a)(2) for a period of no more than seven years from the date the order entered in this matter becomes final, or until the conditions that constituted the violations herein are corrected or are being corrected in accordance with a schedule to which the Commission and the organization have agreed, and all administrative, civil, and criminal penalties and all cleanup and plugging costs incurred by the State relating to those conditions are paid or are being paid in accordance with a schedule to which the Commission and the organization have agreed.

All requested findings of fact and conclusions of law, which are not expressly adopted herein, are denied. All pending motions and requests for relief not previously granted or granted herein are denied.

Oil & Gas Docket No. 09-0319996 Final Order Page 5

Noncompliance with the provisions of this order is subject to enforcement by the Attorney General and subject to civil penalties of up to \$10,000 per day per violation.

R	AT	LROA	T	COMN	MOISSIN	OF TEXAS
$\tau \sim$	ΩЦ.		` '		TI SSILVIN	UP IEXAS

(Signatures	affixed by Default Master	Order
dated	JAN 1 4 2020	)

EMM/bt